

KINGDOM OF BAHRAIN

SURVEY & LAND REGISTRATION BUREAU

HYDRO SURVEY DIRECTORATE



مملكة البحرين
جهاز المساحة والتسجيل العقاري
إدارة المسح البحري

CHART CORRECTION: 01/2019

(HSD-217-01-2019-031 dated 20 February 2019)

Subject: Pilot boarding place near Bahrain Approach Buoy.

Pilot boarding south west of Bahrain Approach Buoy:


Insert



26-21.304N, 050-46.205E

Charts affected: 1505, 5004 (INT 7255), 6501 (INT 7254)

Rashid Abdulla Al Suwaidi
Director
Hydrographic Survey Directorate



2030
البحرين
BAHRAIN




CHART CORRECTION: 02/2019

(HSD-217-01-2019-032 dated 25 February 2019)

Subject: **SUBMARINE CABLE.**

Insert



Submarine cable from Mina Khalifa with 200 meter safety corridor on either side, in position:

26-13.049 N 050-42.055 E
26-13.399 N 050-43.478 E
26-14.203 N 050-43.435 E
26-14.438 N 050-44.288 E
26-15.684 N 050-45.348 E
26-21.874 N 050-45.805 E
26-23.522 N 050-46.593 E
26-25.366 N 050-49.563 E
26-26.919 N 050-51.307 E
26-28.737 N 050-52.167 E
26-29.437 N 050-56.902 E
26-30.115 N 050-59.382 E
26-30.064 N 051-00.086 E

Charts affected: 1501 (INT 7258), 1504, 1505, 1506, 1507, 5004 (INT 7255), 6501 (INT 7245), 10001

Rashid Abdulla Al Suwaidi
Director
Hydrographic Survey Directorate



2030
البحرين
BAHRAIN

KINGDOM OF BAHRAIN

SURVEY & LAND REGISTRATION BUREAU

HYDRO SURVEY DIRECTORATE



مملكة البحرين
جهاز المساحة والتسجيل العقاري
إدارة المسح البحري

CHART CORRECTION: 03/2019

(HSD-217-01-2019-033 dated 28 February 2019)

Subject: Sunken Vessel in the vicinity of South Khor Buoy.

“TSM ANCORA” 70m length has sunk in the vicinity of South Khor Buoy:

Insert  26-12.248N, 050-38.852E

Charts affected: 1501 (INT 7258), 5004 (INT 7255), 10001



Rashid Abdulla Al Suwaidi
Director
Hydrographic Survey Directorate



2030
البحرين
BAHRAIN