



CHART CORRECTION: 02/2024

(HSD-217-01-2024-032 – date: 13 March 2024)

Subject: Establishment of Two New Submarine Pipelines.

Two new submarine pipelines have been established joining the following positions with a 100m safety corridor on both sides of the pipelines.

Insert:

Submarine pipeline, — — — — — , joining:

26-09.165N	50-38.653E
26-09.292N	50-38.695E
26-09.487N	50-39.133E
26-10.945N	50-39.196E
26-11.184N	50-39.257E
26-12.077N	50-39.617E
26-12.087N	50-39.648E

Chart affected: 1501 (INT 7258).



Rashid Abdulla Al Suwaidi
Director
Hydrographic Survey Directorate




CHART CORRECTION: 01/2024

(HSD-217-2023-23-dated 20 February 2024)

Subject: Establishment, Deletion, and Replacement of Aids to Navigation.

New aids to navigation have been established on the following positions.

Insert:



A.	☆ Fl.R.3s	26-09.845N	50-39.653E
B.	☆ Fl.R.3s	26-09.815N	50-39.673E
C.	☆ F.R.7m	26-09.385N	50-40.470E
D.	☆ F.R.7m	26-09.300N	50-40.560E
E.		26-13.831N	50-43.266E
F.	Legend, <i>Seistan Wk</i> , at buoy	26-09.462N	50-43.211E
G.	Legend, L1/NOGA, at beacon	26-09.268N	50-37.979E
H.	Legend, L3/NOGA, at beacon	26-09.429N	50-38.682E



I. Legend, L6/NOGA, at beacon	26-09.628N	50-38.833E
J. Legend, L8/NOGA, at beacon	26-09.732N	50-39.076E
K. Legend, L9/NOGA, at beacon	26-09.954N	50-39.576E
L. Legend, L4/MoH, at beacon	26-09.480N	50-38.657E
M. Legend, L5/ MoH, at beacon	26-09.234N	50-38.109E
N. Legend, L6/ MoH, at beacon	26-09.406N	50-37.878E





Aids to navigation have been deleted from the following positions.

Delete:

A.		26-06.710N	50-39.119E
B.		26-07.280N	50-39.260E

The following aids to navigation have been amended.

Replace:

A.		Hayyan Bn Fl.3s.3m.7M	26-03.174N	50-35.619E	
	With 	Hayyan Al Shaikh	26-03.234N	50-39.096E	
B.		With 	Fl(4)6s GPIC Front	26-09.146N	50-40.706E
C.		With 	Fl(4)10s GPIC Rear	26-09.096N	50-40.681E

KINGDOM OF BAHRAIN

SURVEY & LAND REGISTRATION BUREAU














HYDRO SURVEY DIRECTORATE




مملكة البحرين

جهاز المساحة والتسجيل العقاري

إدارة المسح البحري

D.		With		26-07.564N	50-39.269E
E.		With		26-07.516N	50-39.464E
F.		With		26-06.051N	50-38.801E
G.		With		26-06.040N	50-38.642E
H.		With		26-06.332N	50-37.939E
I.		With		26-06.214N	50-37.837E
J.		With		26-14.161N	50-47.209E

Charts affected: 1501 (INT 7258), 1503 (INT 7261), 5001, 5004 (INT 7255), 6501 (INT 7254), 10001.



Rashid Abdulla Al Suwaidi
Director
Hydrographic Survey Directorate