

CHART CORRECTION: 01/2025

(HSD-217-01-2025-010-Date: 02 Feb 2025)

(Source: MENAS NTM 14-24)

Subject: **Buoy Altered in Position – Mina Salman.**

MSI-2 Buoy has been altered in position:

Move



from

26-11.700 N 050-36.670 E

to

26-11.675 N 050-36.675 E

Charts affected: 1501 (INT 7258)

**Rashid Abdulla Al Suwaidi****Director****Hydrographic Survey Directorate**