



CHART CORRECTION: 01/2021


(HSD-217-01-2021-21 dated 31 January 2021)

Subject: Unlit Steel Pipe.

A dangerous unlit pipe reported in vicinity south of Khalifa Bin Salman Port:

Insert  26-08.822N, 050-42.680E

Charts affected: 1503 (INT 7261), 5004 (INT 7255), 6501 (INT 7254), 10001



Rashid Abdulla Al Suwaidi
Director
Hydrographic Survey Directorate