



CHART CORRECTION: 01/2022

(HSD-217-01-2022-014 dated 26 January 2022)

Subject: **New updates with updated coastline.**

New updates of Bahrain's Charts published on 26 January 2022.
Includes changes: updating the coastline.

Charts affected: 1502 (INT 7259), 1504 (INT 7255), 5001, 5002, 5003, 5004, 6501 (INT 7254), 10001, 2001.

25/1/2022

Rashid Abdulla Al Suwaidi
Director
Hydrographic Survey Directorate



CHART CORRECTION: 02/2022

(HSD-217-01-2022-033 Dated 18 / 04 / 2022)

Subject: Non-Dangerous Wreck Withdrawn North of Bahrain.


A non-Dangerous Wreck have been permanently withdrawn:

Delete:



26-22.400N, 050-53.500E

Charts affected: 6501 (INT 7254)


Rashid Abdulla Al Suwaidi
Director
Hydrographic Survey Directorate

2030
البحرين
BAHRAIN



CHART CORRECTION: 03/2022
(HSD-217-01-2022-059 Date 30 August 2022)

Subject: Amended Navigation Aids Amended in ASRY Channel.

The following Navigation Aids have been amended as below:

- A.  Fl. Y. 1.5s To  Fl(2) Y. 5s 26-12.050 N 50-40.280 E
- B.  Fl(2) Y. 5s To  Fl. Y. 1.5s 26-11.830 N 50-40.400 E

Charts affected: 1501 (INT 7258), 1503 (INT 7261)


Rashid Abdulla Al Suwaidi
Director
Hydrographic Survey Directorate



CHART CORRECTION: 04/2022

HSD-217-01-2022-60

Subject: **Dredging and Reclamation at Investment Gateway Bahrain (IGB)**
Completed.

The dredging and reclamation operation at investment gateway Bahrain (IGB) have been completed.

Delete:

Limit of Works in Progress ~~Work in progress~~ Centered on: 26-15.500 N 50-40.700 E

Charts affected: 1504 (INT 7255), 5004, 6501 (INT 7254), 10001, 15001.

1/7/2022

Rashid Abdulla Al Suwaidi
Director
Hydrographic Survey Directorate

2030
البحرين
BAHRAIN



CHART CORRECTION: 05/2022

(HSD-217-01-2022-89 dated 24 Nov 2022)

Subject: **Amended Buoy Position at Mina Salman channel.**

The position of buoy number 1 have been amended at Mina Salman channel:

Insert:



26-11.580 N

50-39.290 E

Delete:



26-11.655 N

50-39.108 E

Chart affected: 1501 (INT 7258).

Rashid Abdulla Al Suwaidi
Director
Hydrographic Survey Directorate




CHART CORRECTION: 06/2022

(HSD-217-01-2022-93 dated 11. December. 2022)

Subject: Amended Buoy Position at Sitrah Industrial channel.

The position of starboard hand buoy SI-3 has been shifted.

Move:



From: 26-11.328N 50-37.253 E

To: 26-11.310N 50-37.240 E

Chart affected: 1501 (INT 7258).

Rashid Abdulla Al Suwaidi

Director

Hydrographic Survey Directorate

2030
البحرين
BAHRAIN